

# FITNESS CERTIFICATE

To be filled by the Inspecting Officer (Asst. Engineer)

(Re: G.O. Ms. 20/70/PWD Dt. 23-01-1970)

1. Name of the Officer : Arunkumar K S
2. Name of the school : Sivagiri Vidyanikethan Senior  
: Secondary School
3. Location with name of Education District/ Sub District : Keezhmad GP, Aluva, Ernakulam
4. Classification of Building as specified in column 4 of the application for fitness certificate and size : Three Storied RCC Building  
: Details attached
5. Period for which the certificate is issued : 2024-2025
6. Nature of defects if any
  - a. Foundation and basement : Nil
  - b. Superstructure : Nil
  - c. Doors and Windows : Nil
  - d. Wood work wrought and put up : Nil
  - e. Roof : Nil
  - f. Flooring : Nil
  - g. Miscellaneous (Cracks, etc.) : Nil
7. Any major defects noticed which will render the building Unsafe in any manner : Nil
8. Whether maintenance works have been done properly : Yes
9. Whether the structure is sound or not for conducting classes: Sound normal weather conditions

Note: 1. The stability of the structure should be examined also with reference to location, altitude, intensity of wind exposure of flood etc. 2. Any additional observations if deemed necessary for the certificate may be furnished separately with this certificate.

## CERTIFICATE

Certified that the school building was inspected by me on ..... 01/07/2024 ..... and found to be it / unfit to conduct classes, for the period Academic year 2024-2025 reasons stated above.



Place: keezhmad

Date: 01/07/2024

(Seal)

Assistant Engineer

Issuing the provisional fitness only, since the application for the regularisation of the school building is under processing. The building need to be regularised this year itself.



## RCC Building

### 1. Cellar floor

6.70m x 5.25m - 2Nos

### 2. Ground Floor

5.50m x 2.50m - 1 No

5.45m x 4.85 m - 1 No

5.50m x 3.00m - 1 No

7.00m x 6.95 m - 1 No

8.20m x 4.70 m - 1 No

6.35m x 5.90 m - 1 No

6.00m x 5.90 m - 1 No

6.30m x 6.00 m - 1 No

4.70m x 4.00 m - 1 No

11.00m x 7.00 m - 1 No

2.55m x 1.70 m - 1 No

### 3. First floor

7.20m x 6.30 m - 1 No

7.70m x 7.00 m - 1 No

4.70m x 4.00 m - 2 Nos

6.30m x 6.00 m - 12Nos

8.30m x 4.50 m - 1 No

7.30m x 4.10 m - 1 No

11.70m x 7.00 m - 1 No

2.55m x 1.70 m - 1 No

5.55m x 3.60 m - 1 No

6.90m x 5.65 m - 1 No

### 4. Second floor

7.20m x 6.30 m - 1 No

7.70 x 7.00 m - 1 No

8.20m x 4.70 m - 1 No

6.30m x 6.00 m - 12 Nos

8.30m x 4.40 m - 1 No

7.80m x 7.00 m - 1 No

4.25m x 2.50 m - 1 No

14.45m x 7.00 m - 1 No

2.55m x 1.70 m - 1 No

**Total Rooms - 60Nos**

**Total Plinth area 4965 m<sup>2</sup>**

ARUN KUMAR K.S.  
PEN - 882222  
Assistant Engineer  
I.S.O.D  
Keechmad G.P.

